

# SMART SOLUTION (CHINA) LIMITED

Room 312 Fu Li Ying Feng Plaza, A block, No.2 Hua Qiang Road,  
Zhujiang New Town, Tian He District, Guangzhou, China  
Zip Code:510000  
Office: (+86) 020-386-786-98

## REPORT OF INSPECTION

Service No.: YF20160413\_116

Report date: 18th, May 2016

TO: A. GANOV

FROM: E. BOTVENKO

CLIENT CONTRACT No.	YF20160413_116
ORDER QTY.	15000PCS
MANUFACTURER	丹阳市江字工具有限公司
INSPECTION PLACE	Yiwu warehouse
INSPECTION DATE	16/5/17
STYLE NO.	1style
REF.SAMPLE	n/a
INSPECTOR	SMART SOLUTION (CHINA) LIMITED



This product only for part no./

Sampling level: [√]AQL II

### 1.Summary result

Order No.	Part Name	Order qty (sets)	product(pcs)		package(pallet)		sampling size(pcs)	AQL II 1.0/2.5			defects finding(pcs)			Jugement
			finished qty	unfinished qty	packed qty	unpacked qty		Cr	Ma	Mi	Cr	Ma	Mi	
/	Woodworking Hole Saws	15000	15000	0	75	0	315	0	7	14	0	0	2	Pass
Total		15000	15000	0	75	0	315							

### 2. Packaging

Part No.	packing method	result
Woodworking Hole Saws	1pcs/red plastic case,20pcs/pp bags,200pcs/carboard box,carboard box size:350*370*210mm	no material to contrast

### 3. Dimension

Part No.	dimensions	result
Woodworking Hole Saws	see below pictures	no material to contrast

### 4. Relevant tests

Part No.	testing point	by means of	qty(pcs)	result
Woodworking Hole Saws	dimensional measurement	caliper	315	no material to contrast
Woodworking Hole Saws	drop test	operate/visual	1	OK

### 5. Remarks

- As the inspection carried out at warehouse,there is no any testing tool available,like balance,hardness tester,assembly tools,etc.
- We have informed factory to deal with the defects.

### 6. photoes & description

Woodworking Hole Saws

Package













	
	
	
	
Products	









		
		
		
		
Dimension		













relevant test





							
Defects findings							
			Cr	Ma	Mi	defect description	
 					2	with burrs	
Sampling Qty:		315PCS	total		2	Judgement	Pass

SUPPLIER

SMART SOLUTION (CHINA) LIMITED

\_\_\_\_\_

CUSTOMER

"CONTINENT PROJECT CARGO" LLC

\_\_\_\_\_